

FIG. 1




FIG. 2




FIG. 2

FIG. 3





FIG. 4






FIG. 5




FIG. 6




FIG. 7




FIG. 8






FIG. 12





FIG. 13



2025-07-29 15:00

FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20




FIG. 21



0940517 072004
100220 1230160

FIG. 22



0910517 073004 10020" 21501660


OVERLAPPED PART

RANGE COVERED ONLY BY HEAD CHIP B

PAPER FEED DIRECTION


PAPER FEED
DIRECTION

FIG. 24



F00220" 2504660

FIG. 25



091061 072004 00220 01301660

FIG. 26




FIG. 27




FIG. 27

FIG. 28




FIG. 29




FIG. 30




FIG. 31




FIG. 32




FIG. 33




FIG. 30






FIG. 34